



NEWTON FIRE DEPARTMENT
NEWTON, MA

NFIRS Incident #19002752

FDID	State	Incident Date	Station	Incident Number	Exposure	Report Status
17207	MA	04/22/2019		19002752	0	APPROVED

Address

Location Type	STREET ADDRESS		Census Tract	3736
St. Prefix	St. Number	St. Name	St. Type	St. Suffix
	250	HAMMOND POND	PARKWAY	
Apt. Number	Cross Street or Directions			
	City	State	Zip	
	NEWTON	MA	02467	

Incident Details

<u>C: Incident Type</u>	<u>E1: Dates & Times</u>	<u>E2: Shifts & Alarms</u>		
111 BUILDING FIRE	Date/Time	Shift/Platoon	Alarms	District
D: Aid Given/Received	(mm/dd/yyyy hh:mm:ss)	3	2	3
1 MUTUAL AID RECEIVED	Alarm	04/22/2019 12:21:20	<u>Special Study ID#</u>	<u>Special Study Value</u>
Mutual Aid (FDID) Agency - State	Arrival	04/22/2019 12:26:58		
(21046) MA - BROOKLINE FIRE	Controlled		Incident Under Investigation	N
Mutual Aid Incident Number	Last Unit Cleared	04/22/2019 19:49:43		
0				

F: Actions Taken

Primary Action
81 INCIDENT COMMAND
Additional Action -1
11 EXTINGUISH
Additional Action - 2
53 EVACUATE AREA

G1: Resources

	Apparatus	Personnel
Suppression	12	35
EMS	0	0
Other	0	0

G2: Estimated Dollar Losses & Values

LOSSES:

Property \$	1000000
Contents \$	

PRE-INCIDENT VALUE:

Property \$	
Contents \$	

H1: Casualties

	Deaths	Injuries
Fire Service		

H3: Hazardous Materials Release

--

Civilian		
<u>H2: Detector</u>		
<u>I: Mixed Use Property</u>		
<u>J: Property Use</u>		
429 MULTIFAMILY DWELLINGS		

K1: Person/Entity Involved**Person/Entity #: 1**

Business Name	THE TOWERS OF CHESTNUT HILL		Phone Number	
Prefix	First Name	MI	Last Name	Suffix
	St. Num	St.Name	St. Type	
	250	HAMMOND POND	PKY	
	Apt. Number	P.O.Box		
	City		State	Zip
	NEWTON		MASSACHUSETTS	02467
Notes				

K2: Owner

Business Name	THE TOWERS OF CHESTNUT HILL		Phone Number	
Prefix	First Name	MI	Last Name	Suffix
St. Prefix	St. Num	St.Name	St. Type	St. Suffix
	250	HAMMOND POND	PKY	
	Apt. Number	P.O.Box		
	City		State	Zip
	NEWTON		MA	02467

L: Remarks

This fire did not appear suspicious. After all factors of ignition were considered, interviews were taken and a fire pattern burn analysis was performed. The point of origin was determined to be located in the kitchen of 806S, in the area of the range/oven.

It is more likely than not; the cause of the fire was the ignition of drop cloths that were laid out on top of the range. The unit was not being lived in at the time of the fire and workers were present conducting renovations. The owner of the unit Anne Dodson hired the four man crew to remove the textured, popcorn ceiling and install flooring. By the

accounts of two of the workers, Bob Mahar and Paul Mahar, they had put down drop cloths on all surfaces to collect the debris as they scraped the ceilings. They began their work around 0900 and roughly around 1200, while eating their lunch in a nearby bedroom, claimed they heard a loud pop and went to investigate. When they entered the kitchen it was smoky and they saw a large amount of fire above the stove. They stated, it was engulfed in flames. The men left the building and alerted property management that there was a fire.

Bob Mahar told Lois, the property manager who was located in her office on the first floor of the north building, that there was a fire in 806S. Lois went to the unit with a fire extinguisher, attempted to put out the flames but could not. She then exited the unit, closing the door and activated the manual pull station located at the nearest stairwell. This initiated the emergency response and the evacuation of occupants.

The burn patterns and heaviest charring led the investigation to the area of the range. Burnt and smoldering pieces of a drop cloth were found under debris on top of the range. It appeared that the cooktop control knob on the far left was askew, with the potential to activate the surface elements.

The electrical inspector evaluated all outlets, switches, and wiring in the area of the fire finding nothing out of the ordinary.

Considering all potential causes and ignition sources it is more likely than not that the electric range provided the heat source necessary for ignition and the material first ignited included the drop cloths and debris that covered the heating elements.

During the investigation of the scene, it was discovered that there was a delay in notification due to covered smoke detectors within the unit. There also was a delay in fire suppression due to malfunctioning sprinkler heads in the area of the fire.

The make and model of the stove, according to the owners manual was a Samsung NE58F9500SS. It had recently been installed by the head of building maintenance, John Breckner, around January 2019.

M: Authorization

Approved By	Approver Name	Position	Assignment	Date
14153	JIMENEZ I	DEP CH		04/30/2019 16:37:49
Officer in-Charge	Officer Name	Position	Assignment	Date
12669	PROIA B	CHIEF	C-1	04/26/2019 14:31:19
Member ID	Member Name	Position	Assignment	Date
14153	JIMENEZ I	DEP CH	K-1	04/26/2019 14:31:19

Fire Form

Property Information

B: Property Details B1: Estimated Number of living units in building of origin 423 B2: Number of buildings involved Building not involved B3: Acres burned 	C: On-Site Materials or Products None
---	---

D: Ignition D1: Area of fire origin 	E1: Cause of Ignition 2 UNINTENTIONAL	E3: Human Factors Contributing to Ignition None
--	---	---

24 COOKING AREA, KITCHEN	<u>E2: Factors Contributing To Ignition</u>
D2: Heat Source	Factor (1)
10 HEAT FROM POWERED EQUIPMENT, OTHER	52 ACCIDENTALLY TURNED ON, NOT TURNED OFF
D3: Item first ignited	
47 TARPAULIN OR TENT	
D4: Type of material first ignited	
71 FABRIC, FIBER, COTTON, BLENDS, RAYON, WOOL	

F1: Equipment Involved in Ignition		<u>G: Fire Suppression Factors</u>	
646 RANGE, STOVE WITH OR WITHOUT OVEN OR COOKING SURFA		Fire Suppression factor (1)	
Brand	SAMSUNG	520 AUTOMATIC SPRINKLER, STANDPIPE CONNECTION PROBLEM	
Model	NE58F9500SS	Fire Suppression factor (2)	
Serial #		254 PERSONS INTERFERED WITH OPERATIONS	
Year		Fire Suppression factor (3)	
<u>F2: Equipment Power Source</u>		411 DELAYED DETECTION OF FIRE	
ELECTRICAL LINE VOLTAGE (> 50 VOLTS)			

H1: Mobile Property Involved
None

Structure Fire Form

Structure Information

I1: Structure Type	I3: Building Height	
1 ENCLOSED BUILDING	Number of stories at/above grade	17
<u>I2: Building Status</u>	Number of stories below grade	1
2 IN NORMAL USE	<u>I4: Main floor size</u>	
	300(length) BY 300(width)	

J1: Fire Origin Story	J3: Number of stories damaged by flame		K: Material Contributing most to flame spread
8	Minor Damage	1	K1: Item contributung most to flame spread
<u>J2: Fire Spread</u>	Significant Damage	1	23 CABINETRY (INCLUDING BUILT-IN)

4 CONFINED TO BUILDING OF ORIGIN	Heavy Damage	1	K2: Material contributing most to flame spread
	Extreme Damage	1	60 WOOD OR PAPER, PROCESSED, OTHER

L1: Presence of Detectors	L4: Detector Operation
1 PRESENT	3 DETECTOR FAILED TO OPERATE
<u>L2: Detector Type</u>	<u>L5: Detector Effectiveness</u>
1 SMOKE	4 FAILED TO ALERT OCCUPANTS
<u>L3: Detector Power Supply</u>	<u>L6: Detector Failure Reason</u>
4 HARDWIRE WITH BATTERY	4 LACK OF MAINTENANCE, INCLUDES NOT CLEANING

M1: Presence of Automatic Extinguishment System	
1 PRESENT	
<u>M2: Type of Automatic Extinguishment System</u>	<u>M4: Number of Sprinkler Heads</u>
1 WET-PIPE SPRINKLER	3
<u>M3: Automatic Extinguishment System Operation</u>	<u>M5: Automatic Extinguishment System Failure Reason</u>
2 SYSTEM OPERATED AND WAS NOT EFFECTIVE	

Company Reports

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	E1	1

Apparatus	
Apparatus Type	Apparatus Use
(11) ENGINE	(1) SUPPRESSION

Response Address				
St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND POND PKWY	STREET	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS		
Cross Street				

--	--	--

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:39:00	04/22/2019 12:44:17	04/22/2019 19:49:43

Situation Found	
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken

Equipment Used			
Type	Qty.	Measurement	Notes

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
12117	D'AGOSTINO C	CAPT	No	
24827	BRIGHT J C	FF	No	
32865	DEZSO M.	FF	No	

Report Narrative
Assisted in overhaul of fire scene. Assisted building occupants with escorts to obtain personal items from apartments.

Filed By	
Member ID	Member Name
12117	D'AGOSTINO C

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	E10	1

Apparatus	
Apparatus Type	Apparatus Use
(11) ENGINE	(1) SUPPRESSION

Response Address

St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND POND	PARKWAY	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS	02467	
Cross Street				

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:22:14	04/22/2019 12:26:58	04/22/2019 19:49:43

Situation Found	11 BUILDING FIRE
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken
76 PROVIDE WATER

Equipment Used			
Type	Qty.	Measurement	Notes
HOSE 4 IN			

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
25329	CLAFLIN T	FF	No	
39296	DANGELO J	FF	No	
24829	NOTINE A MATTHEW	FF	No	

Report Narrative
<p>engine 10 crew dropped feed line from hydrant out back to the front of building engine 10 crew then assisted moving vehicles and assisting occupants out of the building and retrieving personal items for the occupants</p>

Filed By	
Member ID	Member Name

24829	NOTINE A MATTHEW
-------	------------------

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	E2	1

Apparatus	
Apparatus Type	Apparatus Use
(11) ENGINE	(1) SUPPRESSION

Response Address				
St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND POND	PARKWAY	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS	02467	
Cross Street				

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:39:10	04/22/2019 12:44:19	04/22/2019 18:07:28

<u>Situation Found</u>	11 BUILDING FIRE
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken
20 SEARCH & RESCUE, OTHER
30 EMERGENCY MEDICAL SERVICES, OTHER
53 EVACUATE AREA
70 ASSISTANCE, OTHER
73 PROVIDE MANPOWER

Equipment Used			
Type	Qty.	Measurement	Notes

Company Members Responding

ID	Name	Rank	Acting	Actions Taken
25441	GENTILE M	LT	No	
39218	GIAMPIETRO MATTHEW	FF	No	
25440	GENTILE GARY	FF	No	

Report Narrative

Engine 2 respond to 250 Hammond pond Parkway on the 2nd Alarm. Received orders from Command to capture the elevator and check in with Operations for a possible leg fracture. Determined the elevator was O.O.S. Reported the elevator O.O.S to command and then proceeded to 8th floor via the stairs. Checked in with operations and determined there was no person with a broken leg. We then reported to the 7th floor and checked in with H1. Cleared floors and helped with assisting people to retrieve belongings.

Filed By

Member ID	Member Name
25441	GENTILE M

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	E3	1

Apparatus

Apparatus Type	Apparatus Use
(11) ENGINE	(1) SUPPRESSION

Response Address

St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND	PARKWAY	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS	02467	
Cross Street				

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:22:14	04/22/2019 12:26:58	04/22/2019 18:14:32

<u>Situation Found</u>	
Hydrant Location	

Hydrant Condition	
Hydrant Damaged	No

Actions Taken

Equipment Used			
Type	Qty.	Measurement	Notes

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
25100	CUCCHI P D	LT	No	
38317	GRIFFITHS N	FF	No	
25245	RIFFE J	FF	No	

Report Narrative
<p>Engine 3 was the first due engine on the transmitted box assignment. Enroute, we had smoke showing from Boylston St. and the Chestnut Hill Mall entryway. Upon arrival Engine 3 proceeded to the North Tower with tools and high rise packs. We advanced to Floor 8 via a stairway. We were met with a smoke condition in the hallway where the reported condo unit had a fire. Upon entry of the condo unit, we had a heavy smoke condition in activated sprinkler head in the front foyer. High packs were stretched and charged. Engine 3 along with the first due companies made entry for search and rescue and extinguishment. Engine 3 extinguished the fire, ventilated, and assisted in salvage and overhaul. Engine 3 also assisted in helping displaced occupants with there needs after the fire was extinguished.</p>

Filed By	
Member ID	Member Name
25100	CUCCHI P D

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	E7	1

Apparatus	
Apparatus Type	Apparatus Use
(11) ENGINE	(1) SUPPRESSION

Response Address				
St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250		STREET	

		HAMMOND POND PKWY		
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS		
Cross Street				

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:25:42	04/22/2019 12:26:58	04/22/2019 18:11:26

Situation Found	11 BUILDING FIRE
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken
11 EXTINGUISH
12 SALVAGE & OVERHAUL
22 RESCUE, REMOVE FROM HARM
51 VENTILATE
53 EVACUATE AREA
62 RESTORE SPRINKLER OR FIRE PROTECTION SYSTEM
71 ASSIST PHYSICALLY DISABLED

Equipment Used			
Type	Qty.	Measurement	Notes

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
24830	MELLENDEZ E	LT	No	
30278	HEALY B.	FF	No	
25097	RIZZA K	FF	No	

Report Narrative
<p>E-7 was 3rd due engine on the filled assignment with a report of fire on the 8th floor. E-7 crew assisted E-3 with feeding the FDC, deployed high-rise line off the stairwell riser as backup/second line into kitchen of apartment #806, ventilated using hydraulic ventilation, and overhauled kitchen area alongside E-3, L-2, and R-1. E-7 crew also assisted in</p>

initial evacuation of affected residents in immediate need of evacuation. After fire was knocked down, assisted with shutting down sprinkler water flow and further evacuation of occupants from the south tower. After initial evacuation and determination that power was to remain shut down for an extended period, E-7 assisted occupants with returning to their apartments for needed medication/items and continued evacuation of non-ambulatory residents.

Filed By	
Member ID	Member Name
24830	MELENDEZ E

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	L1	1

Apparatus	
Apparatus Type	Apparatus Use
(12) TRUCK OR AERIAL	(1) SUPPRESSION

Response Address				
St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND POND	PARKWAY	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS	02467	
Cross Street				

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 13:21:00	04/22/2019 13:21:07	04/22/2019 18:12:58

Situation Found	11 BUILDING FIRE
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken	
12	SALVAGE & OVERHAUL
51	VENTILATE
53	EVACUATE AREA
71	ASSIST PHYSICALLY DISABLED

Equipment Used			
Type	Qty.	Measurement	Notes
ASSORTED TOOLS	4		
SCBA	4		

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
18288	LOPEZ T	LT	No	
13038	GOURDEAU E	FF	No	
30704	MCGRATH N.	FF	No	
32861	STEPHENS J	FF	No	

Report Narrative
<p>Ladder One responded on the working fire. Upon arrival we were ordered to the 7th floor to meet H1. We relieved Ladder 3 as the RIT. We were then sent to the upper floors to conduct the secondary search. We forced the door to the unit directly opposite the fire room and it was negative. We continued to search the other floors and assisted in the evacuation of the entire building.</p>

Filed By	
Member ID	Member Name
18288	LOPEZ T

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	L2	1

Apparatus	
Apparatus Type	Apparatus Use
(12) TRUCK OR AERIAL	(1) SUPPRESSION

Response Address				
St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND POND PKWY	STREET	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS		

Cross Street	
---------------------	--

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:22:14	04/22/2019 12:26:58	04/22/2019 19:49:43

Situation Found	11 BUILDING FIRE
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken

Equipment Used			
Type	Qty.	Measurement	Notes

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
25070	BINNALL R J	CAPT	No	
30420	FRANKS Z.	FF	No	
32862	MCCABE S.	FF	No	
38320	LUCCHETTI L	FF	No	

Report Narrative
<p>On arrival L2 went to the fire floor and used the TIC to do a primary search of the fire area. After this came up negative we used the camera to help E 3 find the seed of the fire. We then forced the door on the adjoining apartment checking for extension. L2 's crew then helped with overhaul and escorting occupants to their apartments to retrieve personal belongings.</p>

Filed By	
Member ID	Member Name
25070	BINNALL R J

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	L3	1

Apparatus

Apparatus Type	Apparatus Use
(12) TRUCK OR AERIAL	(1) SUPPRESSION

Response Address				
St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND POND	PARKWAY	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS	02467	
Cross Street				

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:25:42	04/22/2019 12:26:58	04/22/2019 18:05:39

Situation Found	11 BUILDING FIRE
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken
12 SALVAGE & OVERHAUL
51 VENTILATE
53 EVACUATE AREA

Equipment Used			
Type	Qty.	Measurement	Notes

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
11822	FITZGERALD K	LT	No	
21378	GIMENEZ R	FF	No	
38586	WALSH, M.	FF	No	
30108	ARPINO CLIFFORD	FF	No	

--

Report Narrative

Ladder 3 responded on the initial response. L3 was the initial RIT. L3 was relieved as RIT by a Brookline Ladder. L3 assisted with ventilation and overhaul after the fire was extinguished. L3 then assisted with the evacuation of the south tower. L3 used 4 scba's and the RIT gear. All equipment accounted for and no injuries to report.

Filed By

Member ID	Member Name
11822	FITZGERALD K

Agency	Incident Number	Exposure	Unit ID	Report Number
NWT-FD	19002752	0	R1	1

Apparatus

Apparatus Type	Apparatus Use
(71) RESCUE UNIT	(1) SUPPRESSION

Response Address

St. Prefix	St. Num	St. Name	St. Type	St. Suffix
	250	HAMMOND POND PKWY	STREET	
	Apt. Number			
	City	State	Zip	
	NEWTON	MASSACHUSETTS		
Cross Street				

Dispatch Time	Arrival Time	Cleared Time
04/22/2019 12:22:14	04/22/2019 12:26:58	04/22/2019 18:45:40

<u>Situation Found</u>	11 BUILDING FIRE
Hydrant Location	
Hydrant Condition	
Hydrant Damaged	No

Actions Taken

11 EXTINGUISH
51 VENTILATE
86 INVESTIGATE

Equipment Used			
Type	Qty.	Measurement	Notes

Company Members Responding				
ID	Name	Rank	Acting	Actions Taken
18290	TRUDO J	LT	No	
24831	CHAGNON R JR.	FF	No	
32869	ROONEY R.	FF	No	
39070	DONAHUE R	FF	No	

Report Narrative
<p>R-1 responded on the straight box, got report on arrival from building manager of fire on the 8th floor. Made our way to the fire floor assisted E-3 with their high rise hose lines, sprinklers were activated in Rm #807. Worked along with E-3, L-2 and E-7's crews in extinguishing the fire in the kitchen, ventilation of the fire floor and overhaul. After fire was all out R-1 assisted with complete evacuation of the south tower, then when it was deemed safe assisted building occupants with getting needed items from their units</p>

Filed By	
Member ID	Member Name
18290	TRUDO J

Attachments

ATTACHMENTS

ATTACHMENT #: 1

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
DOCUMENT	04/29/2019 11:38:00	JASSET J	
Media: getdocmedia.jsp?agencyname=NWT-FD&incnum=19002752&expnum=0&attachmentnum=1			

ATTACHMENT #: 2

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
-------------	--------------------------	-------------------	--------------------

DOCUMENT 04/29/2019 11:40:00 JASSET J
Media: getdocmedia.isp?agencyname=NWT-FD&incnum=19002752&expnum=0&attachmentnum=2

ATTACHMENT #: 3

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:40:00	JASSET J	

**ATTACHMENT #: 4**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:40:00	JASSET J	

**ATTACHMENT #: 5**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:41:00	JASSET J	




**ATTACHMENT #: 6**

TYPE
PHOTO

DATE/TIME ENTERED
04/29/2019 11:41:00

ENTERED BY
JASSET J

CAPTURED BY

**ATTACHMENT #: 7**

TYPE
PHOTO

DATE/TIME ENTERED
04/29/2019 11:41:00

ENTERED BY
JASSET J

CAPTURED BY

**ATTACHMENT #: 8**

TYPE
PHOTO

DATE/TIME ENTERED
04/29/2019 11:41:00

ENTERED BY
JASSET J

CAPTURED BY



**ATTACHMENT #: 9**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:41:00	JASSET J	


**ATTACHMENT #: 10**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:42:00	JASSET J	

**ATTACHMENT #: 11**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:42:00	JASSET J	



**ATTACHMENT #: 12**

TYPE **DATE/TIME ENTERED**
PHOTO 04/29/2019 11:42:00

ENTERED BY
JASSET J

CAPTURED BY

**ATTACHMENT #: 13**

TYPE **DATE/TIME ENTERED**
PHOTO 04/29/2019 11:42:00

ENTERED BY
JASSET J

CAPTURED BY

**ATTACHMENT #: 14**

TYPE **DATE/TIME ENTERED**


ENTERED BY

CAPTURED BY

PHOTO

04/29/2019 11:42:00

JASSET J

**ATTACHMENT #: 15****TYPE****DATE/TIME ENTERED****ENTERED BY****CAPTURED BY**

PHOTO

04/29/2019 11:43:00

JASSET J

**ATTACHMENT #: 16****TYPE****DATE/TIME ENTERED****ENTERED BY****CAPTURED BY**

PHOTO

04/29/2019 11:45:00

JASSET J




ATTACHMENT #: 17

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>
PHOTO	04/29/2019 11:46:00

<u>ENTERED BY</u>
JASSET J

<u>CAPTURED BY</u>

**ATTACHMENT #: 18**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>
PHOTO	04/29/2019 11:46:00

<u>ENTERED BY</u>
JASSET J

<u>CAPTURED BY</u>

**ATTACHMENT #: 19**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>
PHOTO	04/29/2019 11:46:00


<u>ENTERED BY</u>
JASSET J

<u>CAPTURED BY</u>




ATTACHMENT #: 20


<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:47:00	JASSET J	

**ATTACHMENT #: 21**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:47:00	JASSET J	


**ATTACHMENT #: 22**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:47:00	JASSET J	




**ATTACHMENT #: 23**


<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:47:00	JASSET J	

**ATTACHMENT #: 24**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:47:00	JASSET J	


**ATTACHMENT #: 25**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:47:00	JASSET J	




**ATTACHMENT #: 26**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:48:00	JASSET J	

**ATTACHMENT #: 27**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:48:00	JASSET J	


**ATTACHMENT #: 28**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:48:00	JASSET J	




**ATTACHMENT #: 29**


<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:48:00	JASSET J	


**ATTACHMENT #: 30**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:48:00	JASSET J	


**ATTACHMENT #: 31**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:48:00	JASSET J	




**ATTACHMENT #: 32**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:49:00	JASSET J	

**ATTACHMENT #: 33**


<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:49:00	JASSET J	

**ATTACHMENT #: 34**


<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:49:00	JASSET J	

**ATTACHMENT #: 35**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:49:00	JASSET J	

**ATTACHMENT #: 36**


<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:49:00	JASSET J	

**ATTACHMENT #: 37**


<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:50:00	JASSET J	

**ATTACHMENT #: 38**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:50:00	JASSET J	


**ATTACHMENT #: 39**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:50:00	JASSET J	




ATTACHMENT #: 40

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:50:00	JASSET J	

**ATTACHMENT #: 41**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:51:00	JASSET J	


**ATTACHMENT #: 42**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:51:00	JASSET J	




**ATTACHMENT #: 43**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:51:00	JASSET J	

**ATTACHMENT #: 44**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:51:00	JASSET J	


**ATTACHMENT #: 45**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:52:00	JASSET J	




**ATTACHMENT #: 46**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:52:00	JASSET J	

**ATTACHMENT #: 47**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:52:00	JASSET J	

**ATTACHMENT #: 48**

<u>TYPE</u>	<u>DATE/TIME ENTERED</u>	<u>ENTERED BY</u>	<u>CAPTURED BY</u>
PHOTO	04/29/2019 11:52:00	JASSET J	



**ATTACHMENT #: 49****TYPE**

PHOTO

DATE/TIME ENTERED

04/29/2019 11:52:00

ENTERED BY

JASSET J

CAPTURED BY